


Moving Coil Galvanometer-

It is a device used for the detection and measurement of the currents.



PRINCIPLE- It works on the principle that when a current carrying coil is placed in uniform magnetic field torque experienced on it.

Theory-

In equilibrium, deflecting torque = restoring torque

$$\text{Deflecting torque} = BINA \sin \theta \dots\dots\dots(i)$$

Where,

N = number of turns in the coil,

B = magnetic field intensity,

A = area of cross-section of the coil and

θ = angle between magnetic field and area of the coil

suppose α is the deflection when torque experienced on the coil then,

$$\text{restoring torque} = k \alpha \dots\dots\dots(ii), \text{ where } k \text{ is the tortional constant}$$

$$\text{from eq. (i) and(ii) } BINA \sin \theta = k\alpha$$

because there is always a radial magnetic field, therefore $\theta=90^\circ$, so

$$BINA = k\alpha,$$

$I \propto \alpha$ (current is proportional to the angle of deflection).

Here, k/BNA is known as the figure of merit.

Current Sensitivity

The deflection produced per unit current in galvanometer is called its current sensitivity.

Current sensitivity

$$I_s = \alpha / I = NBA / K$$

Voltage Sensitivity

The deflection produced per unit voltage applied across the ends of galvanometer is called its voltage sensitivity.

Voltage sensitivity

$$V_s = \alpha / V = NBA / KR$$

where R is the resistance of the galvanometer.

Therefore for a sensitive galvanometer

- (i) N should be large (ii) B should be large (iii) A should be large (iv) K should be small


Ammeter -

An ammeter is a low resistance galvanometer used for measuring the current in a circuit.

It is always connected in series.

Conversion of a Galvanometer into an Ammeter

A galvanometer can be converted into an ammeter by connecting a low resistance into its parallel.



If G is the resistance of a galvanometer and it give full scale deflection for current, I_g then required low resistance S, connected in its parallel for converting it into an ammeter of range I is given by

The resistance of an ideal ammeter is zero.

Voltmeter

A voltmeter is a high resistance galvanometer used for measuring the potential difference between two points.

It is always connected in parallel.

The resistance of an ideal voltmeter is infinity. Conversion of a Galvanometer into a Voltmeter

A galvanometer can be converted into a voltmeter by connecting a high resistance into its series. If a galvanometer of resistance G show full scale deflection for current I_g then required high resistance

R, connected in series for converting it into a voltmeter of range V is given by

